



PHOTO 1



PHOTO 2

The open wooden crate attached to the side of the corrugated cardboard package was removed and not surveyed.



PHOTO 3



PHOTO 4

The wooden frames and metal cables were removed in order to check the contents within the corrugated cardboard package.



PHOTO 5



PHOTO 6



PHOTO 7



PHOTO 8

The contents within the corrugated cardboard package



PHOTO 9



PHOTO 10

The staff of Consignee checking through the contents



PHOTO 11



PHOTO 12

The staff of Consignee checking through the contents. The platform of the elevator as per 'Yellow Arrow'.



PHOTO 13

The underneath of the elevator's platform as per 'Yellow Arrow'



PHOTO 14

The plastic sheet was in between the platform of the elevator and the torn opened hole of the package



PHOTO 15



PHOTO 16

There was a scratch mark on the underneath of the elevator's platform as per 'Yellow Circles'



PHOTO 17

Close up view of Photo 16



PHOTO 18

The support beam of the elevator found with scratch marks as per 'Yellow & Red Circles'



PHOTO 19



PHOTO 20

The support beam of the elevator found with scratch marks as per 'Red Circle'



PHOTO 21



PHOTO 22

The support beam of the elevator found with scratch marks as per 'Yellow Circle'



PHOTO 23



PHOTO 24

A photo showing the contents from the corrugated cardboard package